


■ COPPER SLEEVE

**COPPER
FORMED**



ITEM	A (CABLE)	L	CRIMPS
CP262-02	1/16"	0.38"	2
CP262-03	3/32"	0.40"	3
CP262-04	1/8"	0.55"	3
CP262-06	3/16"	0.95"	3
CP262-08	1/4"	1.11"	MACHINE SWAGE
CP262-09	5/16"	1.15"	MACHINE SWAGE
CP262-10	3/8"	1.24"	MACHINE SWAGE